



State of Utah

SPENCER J. COX
Governor

DEIDRE M. HENDERSON
Lieutenant Governor

Department of Natural Resources
Division of Oil, Gas and Mining

JOEL FERRY
Executive Director

MICK THOMAS
Division Director

**Minerals Regulatory Program
Inspection Report**

Mine Name: Velvet	Inspection Date: 12/10/2025
Permit Number: M0370040	Lead Inspector: Tabitha Hatch
Mine Status: Active	Secondary Inspector(s): Steve Demczak, Bailee Jones
Operator: Anfield Resources Holding Corp	Prior Inspection:
Attendee(s): Carrie Williams	Permit Fees: Paid
Weather: Sunny	Bond Amount: \$ 539,000
Reviewed By:	Bond Escalation: 10/26/2030
Conclusions and Recommendations: At the time of the inspection it was observed that the silt fences were not properly installed, the fencing around the portal was not anchored or locked, and there was trash in the waste pile. These issues will need to be addressed by the next inspection.	

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
Permit is up to date.	
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
At the time of the inspection the portal was fenced off, but the fence was not anchored to the ground and had large gaps underneath. The inner gate blocking the portal entrance did not appear to have a lock on it. Not properly sealing the portal is a public safety concern and will need to be fixed by the date of the next inspection. Additionally, trash was observed in the waste pile and will need to be disposed of by the date of the next inspection.	
3. Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
Silt fence is not properly installed and will need to be fixed before the next inspection.	
4. Deleterious Material	<input checked="" type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
No deleterious materials were observed at the time of inspection.	
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
No issues regarding the roads were observed at the time of the inspection.	
6. Reclamation	<input checked="" type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
Reclaimed area looks good.	
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement



8. Soils	<input type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
9. Revegetation	<input type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement
10. Other	<input type="checkbox"/> Evaluated & Commented <input type="checkbox"/> Enforcement

Location



Pictures





Latitude: 38.11775004555555, Longitude: -109.17077175
Road off to the left upon entrance. It is staked.



Latitude: 38.117668326111115, Longitude: -109.1706001388889
Silt fence must be redone. Gap underneath.



Latitude: 38.11762666111111, Longitude: -109.17059908888889
Gap closeup.



Latitude: 38.11752874444444, Longitude: -109.17047293611111
More gaps.



Latitude: 38.11718052055556, Longitude: -109.17017363055557
Truck area.



Latitude: 38.117175311666664, Longitude: -109.17017930555556
Check-in office.



Latitude: 38.117176713333336, Longitude: -109.17017224722223
Onsite vehicles.



Latitude: 38.116981865833333, Longitude: -109.17002965555557
Berms look good.



Latitude: 38.11675106777778, Longitude: -109.16964603611112
Backside of truck area.



Latitude: 38.11658213888889, Longitude: -109.17061233333334
Portal. Fence is not anchored and there is a large gap.



Latitude:, Longitude:
Site overview.



Latitude: , Longitude:
Reclaimed area.



Latitude: , Longitude:
More silt fence gaps.



Latitude: , Longitude:
More gaps.



Latitude: , Longitude:
Trash in waste pile.



Latitude: , Longitude:
More trash.



Latitude: , Longitude:
More trash.



Latitude: , Longitude:
More trash.

Inspector Signature:



Suggestions/Edits:

Reviewer:

CC: Joshua Bleak (josh.bleak@gmail.com);
John Eckerlesy (johneckersley9@gmail.com);
Carl Warren (cwarren@brsengineering.com);
Lanie Lynn-Duque (MLynnDuque@brsengineering.com);
Tina A. Marian (tmarian@blm.gov);
TLA (TLA-ML@utah.gov) ML43977 ML54557-OBA;
Larry Garahana (lgarahan@blm.gov);
BLM Utah State Office ([blm ut so solidsbonds@blm.gov](mailto:blm_ut_so_solidsbonds@blm.gov)) UTU-68060
UTUT106098800

Bailee Jones (baileejones@utah.gov)

P:\GROUPS\MINERALS\WP\M037-SanJuan\M0370040-Velvet\inspections\INSP-12102025.docx

Signature: Matthew Munson
Matthew Munson (Jan 2, 2026 14:39:37 MST)

Email: mmunson@utah.gov

