

17 August, 2015 08:50

The RWT sent from NPR as the weekly test for connectivity between Wyoming Public Radio and NPR (our designated PEP) was not received. The satellite receiver (an SR2000; part of the bank of receivers of which the channel selection is fixed-tuned) was found to be de-tuned as were all the other SR2000 receivers. The reason why is impossible to determine from the logs. Since all SR2000s were affected, it seems more likely there was a fault with the signal or corrupted data sent on the channel, or perhaps a coding flaw in the SR2000 firmware instead of an actual failure with the individual receiver equipment, itself.

Reid Fletcher  
WPR Engineering