

EAS Log Addendum
11:26 AM 9 March, 2015

No EAS Required Weekly Test (RWT) was received from NOAA/NWS for the logging period 1 March through 7 March 2015. The Dayton receiver, used for the reception of signals from both the NOAA/NWS and KOWB/KCGY to recover audio for input to the KUWR and KUWL/KUWY EAS ENDECs, was found to have failed completely.

The NOAA receiver for WXM-37 155.55 MHz is logged as out of service as of the time of this addendum to the station EAS log.

A suitable replacement or substitute will be acquired and installed.

Reid Fletcher
Chief Engineer