

EAS Log Addendum  
16 March, 2015

No EAS Required Weekly Test (RWT) was received from NOAA/NWS for the logging period 1 March through 7 March 2015. The Dayton receiver, used for the reception of signals from both the NOAA/NWS and KOWB/KCGY to recover audio for input to the KUWR and KUWL/KUWY EAS ENDECs, was found to have failed completely. It remains logged out of service as of 9 March 2015. In addition, the antenna has been found to be performing inadequately and will have to be replaced as well. Replacement of the receiver has not yet been done.

Reid Fletcher  
Chief Engineer