

EAS Log Addendum
6 April 2015

A replacement for the failed NWS/NOAA receiver has been obtained and placed into operation. The RWT Wednesday is expected to confirm proper configuration and operation.

Reid Fletcher
Wyoming Public Media Engineering