

30 December, 2015 10:20

The RWT normally sent from NOAA/NWS Cheyenne as the weekly test for connectivity between Wyoming Public Radio and WXM37 (our designated NOAA assignment) was not received. The 155.55 receiver input to the SAGE ENDEC was checked. Audio input to the ENDEC was present, was the correct signal, and was of sufficient level and quality for the ENDEC to successfully decode.

The RWT normally sent from KOWB 1290/KCGY 95.1 Laramie as the weekly test for connectivity between Wyoming Public Radio and WXM37 (our designated NOAA assignment) was also not received. The Inovonics receiver input to the SAGE ENDEC was checked. Audio input to the ENDEC was present, was the correct audio signal, and was of sufficient level and quality for the ENDEC to successfully decode. A telephone query about the time of transmission of their test was made to KOWB but no response has been received as of yet.

Reid Fletcher
WPR Engineering